

Test Date	BEECN/FS #	BEECN/FS Name	Issue	Assign
9/24/2016	SW-33	Collins View	BEECN site should be in parking lot, not ball field; note on profile (& next postcard)	Jones/JVK
9/24/2016	NE-10	Columbia Site Field	Dead UHF radio batteries + key to pump house not working	Jones
1/28/2017	SW-29	Sunstone School	No signal between site and fire station; testing needed	Jones
1/28/2017	FS 19	Mt. Tabor	Wrench for Go Kit (to loosen exterior antenna cap); cap loosened, no wrench needed	Jones
1/28/2017	FS 15	Portland Heights	iCOM IC-2200 Template needs updating (MC1/MC2 reversed)	Jones
1/28/2017	SW-24	Ainsworth School	Lock to door needs graphite	Jones
1/28/2017	FS 4 + SE-35	PSU + Brooklyn Park	Consider re-assigning this and other UHF frequencies/channels to avoid doubling	Jones
1/28/2017	SE-40	Harrison Park	Poor radio signal	Jones
4/25/2017	FS 2	Parkrose	Go Kit UHF radio not flashed properly (channel 1, specifically); swap it out	Jones
6/24/2017	SW-31	Holly Farm Park	Poor radio signal; does fire station or BEECN site(s) need better antenna or other?	Jones
6/24/2017	FS 28	Rose City Hollywood	No signal between site and fire station (VHF radio template, signal issue?)	
7/20/2017	FS 24	Overlook/Swan Is	Is the UHF radio in the Go Kit?	Jones
7/20/2017	FS 24	Overlook/Swan Is	The FS lightning arrestor not connected to ground plate; Ground plate connected to a ground?	
6/24/2017	FS 11	Lents	Power cord on VHS radio misconfigured (AC power + Anderson poles not right)	Jones
10/1/2017	SE-46	Gilbert Heights	Sked hardware needs to be added to Sked	Jones
10/29/2017	FS 30	Gateway	UHF Radio corroded - replace it.	Jones
10/29/2017	FS 30	Gateway	Rust at the bottom of the antenna cable where it attaches to the lightning arrestor. Antenna needs checknig (+ remove pipe cover from jack)	Jones/Picard
10/29/2017	N-6	UP	Key safe not opening (wrong combination?)	Jones
10/29/2017	N-5	St. Johns	Flat tires on cache box	Jones
10/29/2017	FS 2	FS Training Center	if the radio is on the high-power setting, it turns itself off as soon as you key up. When the transmit power is changed to Med. or Low, it works fine	