



Piezometer and Staff Gauge Locations  
 Oaks Bottom  
 BES 8576

- SP-3 Standpipe piezometer
- ◆ S-1 Staff gauge
- P-1 VW Piezometer
- ▲ Water Control Structure