



Nick Fish, Commissioner  
Michael Stuhr, P.E., Administrator

1120 SW 5<sup>th</sup> Avenue, Room 600  
Portland, Oregon 97204-1926  
Information: 503-823-7404  
[www.portlandoregon.gov/water](http://www.portlandoregon.gov/water)



May 22, 2017

Chris Silkie, PE, LEED AP, CEM  
Asset Management Program Manager  
Portland Parks & Recreation  
6437 SE Division St, Suite 416  
Portland, OR 97206

RE: Follow-up Sample Results for Multnomah Arts Center

Dear Chris,

Attached you will find the lead results for the follow-up water samples collected at Multnomah Arts Center on May 11, 2017. Samples were collected in accordance with the protocol outlined in the EPA Technical Guidance, *3Ts for Reducing Lead in Drinking Water in Schools*. The samples were subsequently analyzed at the Portland Water Bureau Laboratory via EPA Method 200.8, an approved method for the analysis of lead in drinking water.

The lead results from these follow-up samples are intended to provide additional information on the possible source(s) which are contributing lead to water in your facility. Information on the interpretation of these results, as well as possible mitigation strategies, are outlined in the EPA guidance – *3Ts for Reducing Lead in Drinking Water in Schools*.

We encourage you to share these results with the public as soon as possible.

Please let us know if you have any questions on these results or any of the other information provided here.

Sincerely,

Yone Akagi, P.E.  
Water Quality Manager  
Portland Water Bureau



**Portland Water Bureau  
Laboratory Report**

OR 100014

**Multnomah Arts Center**

<b>PWB Sample ID</b>	<b>Location Description</b>	<b>Date Collected</b>	<b>Time Collected</b>	<b>Lead Result (ppb)</b>	<b>Sample Type</b>
BB88850	RM 7 Sink (1-7-SINK-1)	5/11/2017	8:40:00 AM	13.4	First Draw Sample
BB88851	RM 7 Sink (1-7-SINK-1)	5/11/2017	8:41:00 AM	9.27	30 Second Flowing Sample
BB88852	RM 34 Sink (1-34-SINK-1)	5/11/2017	8:50:00 AM	48.8	First Draw Sample
BB88853	RM 34 Sink (1-34-SINK-1)	5/11/2017	8:51:00 AM	6.6	30 Second Flowing Sample

ppb = parts per billion



Nick Fish, Commissioner  
Michael Stuhr, P.E., Administrator

1120 SW 5<sup>th</sup> Avenue, Room 600  
Portland, Oregon 97204-1926  
Information: 503-823-7404  
[www.portlandoregon.gov/water](http://www.portlandoregon.gov/water)



April 6, 2017

Chris Silkie, PE, LEED AP, CEM  
Asset Management Program Manager  
Portland Parks & Recreation  
6437 SE Division St, Suite 416  
Portland, OR 97206

RE: Sample Results for Multnomah Arts Center

Dear Chris,

Attached you will find the lead results for the water samples collected at Multnomah Arts Center on March 22, 2017. Samples were collected in accordance with the protocol outlined in the EPA Technical Guidance, *3Ts for Reducing Lead in Drinking Water in Schools*. The samples were subsequently analyzed at the Portland Water Bureau Laboratory via EPA Method 200.8, an approved method for the analysis of lead in drinking water.

The EPA recommends follow-up testing if lead concentrations in any sample exceeds 20 parts per billion (ppb) to pinpoint the source(s) of lead contamination in your facility. Steps should be taken to mitigate elevated lead levels. Potential mitigation strategies, as well as sampling protocols, are outlined in the EPA guidance - *3Ts for Reducing Lead in Drinking Water in Schools*.

We encourage you to share these results with the public as soon as possible.

Please let us know if you have any questions on these results or any of the other information provided here.

Sincerely,

Yone Akagi, PE  
Water Quality Compliance Manager

**Multnomah Arts Center**

<b>PWB Sample ID</b>	<b>Location Description</b>	<b>Date Collected</b>	<b>Time Collected</b>	<b>Lead (ppb)</b>
BB85954	RM 22 East Wall Dish Sink (1-KIT-SINK-4)	3/22/2017	7:05:00 AM	0.77
BB85955	RM 22 East Wall Stand Alone Spigot (1-KIT-SINK-5)	3/22/2017	7:06:00 AM	7.69
BB85956	Hallway Fountain between RM 22 & 24 - Left (1-HALL-DF-5)	3/22/2017	7:02:00 AM	<0.05
BB85957	Hallway Fountain between RM 22 & 24 - Right (1-HALL-DF-6)	3/22/2017	7:03:00 AM	<0.05
BB85958	RM 24 Sink (1-24-SINK-1)	3/22/2017	7:00:00 AM	0.93
BB85959	Hallway Fountain across from RM 40 - Left (1-HALL-DF-3)	3/22/2017	7:08:00 AM	<0.05
BB85960	Hallway Fountain across from RM 40 - Right (1-HALL-DF-4)	3/22/2017	7:09:00 AM	<0.05
BB85961	RM 27 Sink (1-27-SINK-1)	3/22/2017	7:11:00 AM	8.24
BB85962	RM 30 Sink (1-30-SINK-1)	3/22/2017	7:15:00 AM	10.2
BB85963	RM 31 Sink (1-31-LAV-1)	3/22/2017	7:16:00 AM	0.49
BB85964	RM 32 Sink (1-32-SINK-1)	3/22/2017	7:17:00 AM	3.03
BB85965	RM 33 Sink (1-33-SINK-1)	3/22/2017	7:19:00 AM	2.89
BB85966	Hallway Fountain between RM 33 & 34 - Left (1-HALL-DF-2)	3/22/2017	7:21:00 AM	0.062
BB85967	Hallway Fountain between RM 33 & 34 - Right (1-HALL-DF-1)	3/22/2017	7:22:00 AM	<0.05
BB85968	RM 34 Sink (1-34-SINK-1)	3/22/2017	7:23:00 AM	40.1
BB85969	RM 35 Sink (1-35-SINK-1)	3/22/2017	7:25:00 AM	8.3
BB85970	RM 38 Sink (1-38-SINK-1)	3/22/2017	7:27:00 AM	5.01
BB85971	RM 39 Sink (1-39-SINK-1)	3/22/2017	7:29:00 AM	0.49
BB85972	RM 41 Kitchen Sink (1-41KT-SINK-1)	3/22/2017	7:32:00 AM	6.91
BB85973	RM 2 Sink (1-2KT-SINK-1)	3/22/2017	7:34:00 AM	2.28
BB85974	RM 5 Sink (1-5-SINK-1)	3/22/2017	7:36:00 AM	5.2
BB85975	RM 7 Sink (1-7-SINK-1)	3/22/2017	7:39:00 AM	28.3
BB85976	RM 9 Sink - Left (1-9-SINK-1)	3/22/2017	7:40:00 AM	2.52
BB85977	RM 9 Sink - Right (1-9-SINK-2)	3/22/2017	7:41:00 AM	1.07
BB85978	RM 10 Sink (1-10-SINK-1)	3/22/2017	7:43:00 AM	2.67
BB85979	West Hallway Fountain-Left (1-HALL-DF-7)	3/22/2017	7:47:00 AM	<0.05
BB85980	West Hallway Fountain - Right (1-HALL-DF-8)	3/22/2017	7:48:00 AM	<0.05
BB85981	West Hallway Fountain - Bottle Filler (1-HALL-BF-8)	3/22/2017	7:48:00 AM	<0.05
BB85982	RM 18b Basement Sink (B-18-SINK-1)	3/22/2017	7:50:00 AM	10.1
BB85983	Outside Drinking Fountain (1-OUT-DF-1)	3/22/2017	8:25:00 AM	0.85
BB85984	RM 14 - Left Sink (1-14-SINK-1)	3/22/2017	8:03:00 AM	1.04
BB85985	RM 14 - Right Sink (1-14-SINK-2)	3/22/2017	8:04:00 AM	1.06
BB85986	RM 13 - Left Sink (1-13-SINK-1)	3/22/2017	7:57:00 AM	1.94
BB85987	RM 13 - Center Sink (1-13-SINK-2)	3/22/2017	7:58:00 AM	0.85
BB85988	RM 13 - Right Sink (1-13-SINK-3)	3/22/2017	7:59:00 AM	1.11
BB85989	Glaze Mix Sink - Near RM 13 (1-13-GSINK-1)	3/22/2017	8:01:00 AM	1.21
BB85990	RM 12 Sink (1-12-SINK-1)	3/22/2017	8:06:00 AM	1.27
BB85991	Cottage 1 Main RM Sink (1-COT1-SINK-1)	3/22/2017	8:22:00 AM	2.41
BB85992	Cottage 2 Main RM Sink (1-COT2-SINK-1)	3/22/2017	8:19:00 AM	2.26
BB85993	Cottage 3 Office Sink (1-COT3-SINK-1)	3/22/2017	8:17:00 AM	13
BB85994	Cottage 4 Sink (1-COT4-SINK-1)	3/22/2017	8:14:00 AM	6.3
BB85995	Cottage 5 Sink (1-COT5-SINK-1)	3/22/2017	8:12:00 AM	3.23
BB85996	Cottage 6 Sink - Right (1-COT6-SINK-2)	3/22/2017	8:10:00 AM	1.62

ppb = parts per billion



## Portland Water Bureau Laboratory Report

*Test results from June 2016*

Sample ID	Facility	Location Description	Date Collected	Time Collected	Lead (ppb)	Standing Time (hours)
BB64671	Multnomah Arts Ctr.	RM 22 North Wall Dish Sink (1-KIT-SINK-1)	6/9/16	6:36:00 AM	1.05	10.35
BB64672	Multnomah Arts Ctr.	RM 22 North Hand Sink (1-KIT-SINK-2)	6/9/16	6:37:00 AM	12.4	10.28
BB64673	Multnomah Arts Ctr.	RM 22 Bathroom Sink (1-KTRR-LAV-1)	6/9/16	6:38:00 AM	3.57	10.3
BB64674	Multnomah Arts Ctr.	RM 22 East Wall Dish Sink (1-KIT-SINK-4)	6/9/16	6:39:00 AM	30.4	10.37
BB64675	Multnomah Arts Ctr.	RM 22 East Wall Stand Alone Spigot (1-KIT-SINK-5)	6/9/16	6:40:00 AM	8.91	10.38
BB64676	Multnomah Arts Ctr.	East Front Women's Bathroom - Left Spigot (1-WRRE-LAV-1)	6/9/16	6:43:00 AM	7.93	10.35
BB64677	Multnomah Arts Ctr.	East Front Women's Bathroom - Center Spigot (1-WRRE-LAV-2)	6/9/16	6:44:00 AM	2.96	10.03
BB64678	Multnomah Arts Ctr.	East Front Women's Bathroom - Right Spigot (1-WRRE-LAV-3)	6/9/16	6:45:00 AM	2.68	10
BB64679	Multnomah Arts Ctr.	East Front Men's Bathroom - Left Spigot (1-MRRE-LAV-1)	6/9/16	6:47:00 AM	10.2	10.12
BB64680	Multnomah Arts Ctr.	East Front Men's Bathroom - Center Spigot (1-MRRE-LAV-2)	6/9/16	6:48:00 AM	7.12	10.13
BB64681	Multnomah Arts Ctr.	East Front Men's Bathroom - Right Spigot (1-MRRE-LAV-3)	6/9/16	6:49:00 AM	8.2	10.15
BB64682	Multnomah Arts Ctr.	RM 26 Sink (1-26-SINK-1)	6/9/16	6:50:00 AM	80.5	10.75
BB64683	Multnomah Arts Ctr.	RM 27 Sink (1-27-SINK-1)	6/9/16	6:51:00 AM	6.33	10.78
BB64684	Multnomah Arts Ctr.	RM 27 Fountain (1-27-DF-1)	6/9/16	6:52:00 AM	28.3	10.8
BB64685	Multnomah Arts Ctr.	Faculty Bathroom Sink - Cold Faucet (1-RREH-LAV-1)	6/9/16	6:54:00 AM	4.7	10.78
BB64686	Multnomah Arts Ctr.	East Hall Men's Bathroom (1-RRSE-LAV-1)	6/9/16	6:57:00 AM	2.06	10.42
BB64687	Multnomah Arts Ctr.	East Hall Women's Bathroom (1-RRSE-LAV-2)	6/9/16	6:58:00 AM	2.24	10.43
BB64688	Multnomah Arts Ctr.	RM 29 Closet Sink (1-29-SINK-1)	6/9/16	7:01:00 AM	447	
BB64689	Multnomah Arts Ctr.	RM 31 Sink (1-31-LAV-1)	6/9/16	7:03:00 AM	1.15	11.22
BB64690	Multnomah Arts Ctr.	RM 32 Sink (1-32-SINK-1)	6/9/16	7:04:00 AM	5.25	11.22
BB64691	Multnomah Arts Ctr.	RM 33 Sink (1-33-SINK-1)	6/9/16	7:05:00 AM	91.2	8 to 18
BB64692	Multnomah Arts Ctr.	RM 34 Sink (1-34-SINK-1)	6/9/16	7:09:00 AM	61.6	11.15
BB64693	Multnomah Arts Ctr.	RM 35 Sink (1-35-SINK-1)	6/9/16	7:12:00 AM	9.17	10.72
BB64694	Multnomah Arts Ctr.	RM 37 Sink (1-37-SINK-1)	6/9/16	7:15:00 AM	24.7	11.22
BB64695	Multnomah Arts Ctr.	RM 38 Sink (1-38-SINK-1)	6/9/16	7:16:00 AM	8.26	9.65
BB64696	Multnomah Arts Ctr.	RM 39 Sink (1-39-SINK-1)	6/9/16	7:18:00 AM	0.63	10.63
BB64697	Multnomah Arts Ctr.	RM 41 Sink - Cold Faucet (1-41RR-LAV-1)	6/9/16	7:20:00 AM	8	10.53

Sample ID	Facility	Location Description	Date Collected	Time Collected	Lead (ppb)	Standing Time (hours)
BB64698	Multnomah Arts Ctr.	RM 41 Kitchen Sink (1-41KT-SINK-1)	6/9/16	7:21:00 AM	10.5	10.57
BB64699	Multnomah Arts Ctr.	RM 2 Sink (1-2KT-SINK-1)	6/9/16	7:24:00 AM	5.93	8 to 18
BB64700	Multnomah Arts Ctr.	RM 5 Sink (1-5-SINK-1)	6/9/16	7:26:00 AM	9.82	13.6
BB64701	Multnomah Arts Ctr.	RM 7 Sink (1-7-SINK-1)	6/9/16	7:28:00 AM	15.8	14
BB64702	Multnomah Arts Ctr.	RM 9 Sink - Left (1-9-SINK-1)	6/9/16	7:29:00 AM	5.18	14.37
BB64703	Multnomah Arts Ctr.	RM 9 Sink - Right (1-9-SINK-2)	6/9/16	7:30:00 AM	1.86	14.35
BB64704	Multnomah Arts Ctr.	RM 10 Sink (1-10-SINK-1)	6/9/16	7:31:00 AM	11.2	14.27
BB64705	Multnomah Arts Ctr.	RM 11 Front Sink (1-11B-SINK-1)	6/9/16	7:33:00 AM	54.5	16.35
BB64706	Multnomah Arts Ctr.	RM 11 Back Sink (1-11A-SINK-1)	6/9/16	7:34:00 AM	22.3	16.35
BB64707	Multnomah Arts Ctr.	Janitor Closet Sink - Near DRK RM (1-CLOS-SINK-1)	6/9/16	7:35:00 AM	7.11	16.08
BB64708	Multnomah Arts Ctr.	West Men's Bathroom - Left Spigot (1-MRRW-LAV-1)	6/9/16	7:37:00 AM	9.86	9.95
BB64709	Multnomah Arts Ctr.	West Men's Bathroom - Center Spigot (1-MRRW-LAV-2)	6/9/16	7:37:00 AM	3.24	9.95
BB64710	Multnomah Arts Ctr.	West Men's Bathroom - Right Spigot (1-MRRW-LAV-3)	6/9/16	7:37:00 AM	3.02	9.95
BB64711	Multnomah Arts Ctr.	West Women's Bathroom - Left Spigot (1-WRRW-LAV-1)	6/9/16	7:38:00 AM	8.56	9.98
BB64712	Multnomah Arts Ctr.	West Women's Bathroom - Center Spigot (1-WRRW-LAV-2)	6/9/16	7:39:00 AM	3.94	10
BB64713	Multnomah Arts Ctr.	West Women's Bathroom - Right Spigot (1-WRRW-LAV-3)	6/9/16	7:39:00 AM	3.57	10
BB64714	Multnomah Arts Ctr.	West Hallway Fountain-Left (1-HALL-DF-6)	6/9/16	7:41:00 AM	0.3	16.15
BB64715	Multnomah Arts Ctr.	West Hallway Fountain - Right (1-HALL-DF-7)	6/9/16	7:41:00 AM	0.27	16.15
BB64716	Multnomah Arts Ctr.	West Hallway Fountain - Bottle Filler (1-HALL-DF-8)	6/9/16	7:41:00 AM	0.34	16.15
BB64717	Multnomah Arts Ctr.	RM 18 Backstage Sink (1-RSS-LAV-1)	6/9/16	7:44:00 AM	18.5	16.1
BB64718	Multnomah Arts Ctr.	RM 18b Basement Sink (B-18-SINK-1)	6/9/16	7:45:00 AM	24.1	16.12
BB64719	Multnomah Arts Ctr.	Outside Bathroom Sink (1-OUT-LAV-1)	6/9/16	7:48:00 AM	7.04	8 to 18
BB64720	Multnomah Arts Ctr.	RM 12 Sink (1-12-SINK-1)	6/9/16	7:49:00 AM	4.1	14.08
BB64721	Multnomah Arts Ctr.	Glaze Mix Sink - Near RM 13 (1-13-GSINK-1)	6/9/16	7:50:00 AM	3.15	10.85
BB64722	Multnomah Arts Ctr.	RM 13 - Left Sink (1-13-SINK-1)	6/9/16	7:52:00 AM	0.87	10.92
BB64723	Multnomah Arts Ctr.	RM 13 - Center Sink (1-13-SINK-2)	6/9/16	7:52:00 AM	0.97	10.92
BB64724	Multnomah Arts Ctr.	RM 13 - Right Sink (1-13-SINK-3)	6/9/16	7:52:00 AM	2.33	10.92
BB64725	Multnomah Arts Ctr.	RM 14 - Left Sink (1-14-SINK-1)	6/9/16	7:53:00 AM	2.9	10.98
BB64726	Multnomah Arts Ctr.	RM 14 - Right Sink (1-14-SINK-2)	6/9/16	7:53:00 AM	2.94	10.98
BB64727	Multnomah Arts Ctr.	Outside Drinking Fountain (1-OUT-DF-1)	6/9/16	7:55:00 AM	1.85	16.5
BB64728	Multnomah Arts Ctr.	Cottage 1 Main RM Sink (1-COT1-SINK-1)	6/9/16	8:00:00 AM	3.71	14.63
BB64729	Multnomah Arts Ctr.	Cottage 1 Bathroom Sink (1-COT1-LAV-1)	6/9/16	8:00:00 AM	4.72	14.6
BB64730	Multnomah Arts Ctr.	Cottage 2 Main RM Sink (1-COT2-SINK-1)	6/9/16	8:02:00 AM	3.21	14.6

<b>Sample ID</b>	<b>Facility</b>	<b>Location Description</b>	<b>Date Collected</b>	<b>Time Collected</b>	<b>Lead (ppb)</b>	<b>Standing Time (hours)</b>
BB64731	Multnomah Arts Ctr.	Cottage 2 Bathroom Sink (1-COT2-LAV-1)	6/9/16	8:03:00 AM	1.36	14.6
BB64732	Multnomah Arts Ctr.	Cottage 3 Office Sink (1-COT3-SINK-1)	6/9/16	8:05:00 AM	4.82	14.58
BB64733	Multnomah Arts Ctr.	Cottage 3 Women's Bathroom - Left Sink (1-COT3-WLAV-1)	6/9/16	8:06:00 AM	4.67	14.6
BB64734	Multnomah Arts Ctr.	Cottage 3 Women's Bathroom - Center Sink (1-COT3-WLAV-2)	6/9/16	8:06:00 AM	3.13	14.6
BB64735	Multnomah Arts Ctr.	Cottage 3 Women's Bathroom - Right Sink (1-COT3-WLAV-3)	6/9/16	8:07:00 AM	2.3	14.62
BB64736	Multnomah Arts Ctr.	Cottage 3 Janitor Sink (1-COT3-JSINK-1)	6/9/16	8:08:00 AM	4.12	14.58
BB64737	Multnomah Arts Ctr.	Cottage 3 Men's Bathroom - Left Sink (1-COT3-MLAV-1)	6/9/16	8:09:00 AM	7.07	14.57
BB64738	Multnomah Arts Ctr.	Cottage 3 Men's Bathroom - Center Sink (1-COT3-MLAV-2)	6/9/16	8:10:00 AM	20	14.58
BB64739	Multnomah Arts Ctr.	Cottage 3 Men/s Bathroom - Right Sink (1-COT3-MLAV-3)	6/9/16	8:10:00 AM	3.32	14.58
BB64740	Multnomah Arts Ctr.	Cottage 4 Sink (1-COT4-SINK-1)	6/9/16	8:12:00 AM	6.23	14.55
BB64741	Multnomah Arts Ctr.	Cottage 5 Sink (1-COT5-SINK-1)	6/9/16	8:13:00 AM	2.7	14.55
BB64742	Multnomah Arts Ctr.	Cottage 6 Wash Sink - Left (1-COT6-SINK-1)	6/9/16	8:15:00 AM	8.05	14.57
BB64743	Multnomah Arts Ctr.	Cottage 6 Sink - Right (1-COT6-SINK-2)	6/9/16	8:15:00 AM	8.95	14.57
BB64744	Multnomah Arts Ctr.	RM 22 West Closet Sink (1-KIT-SINK-4)	6/9/16	6:35:00 AM	13.7	

ppb = parts per billion

## Multnomah Arts Center water test results – December 2016

### Appendix A: Lead in Drinking Water Sampling Table

Location Description (Water Outlet Code)	Outlet Common Name	First Draw Results (ppb)	Post Screen- Cleaning First Draw Results (ppb)	Flush Results (ppb)	Remediation Action	Post Remediation First Draw Results (ppb)	Remediation Complete (Y/N)
RM 30 Sink (1-30-SINK-1)	Room 30 - Multi-Purpose Room, Sink	<b>20*</b>	-	6.8	Replaced fixture	6.64	Y
RM 18b Basement Sink (B-18-SINK-1)	Room 18b Basement Costume Room, Sink	<b>24.1*</b>	-	6.1	Replaced fixture	11.8	Y
RM 33 Sink (1-33-SINK-1)	Room 33 - Multi-Purpose Room, Sink	<b>91.2*</b>	-	7.2	Replaced fixture	14.5	Y
RM 37 Sink (1-37-SINK-1)	Room 37 - Student Room, Sink	<b>24.7*</b>	<b>77.9</b>	7.3	Removed - Sink Not Required	-	Y
RM 26 Sink (1-26-Sink-1)	Room 26 - Weaving, Sink	<b>80.5*</b>	<b>58.1</b>	4	Removed - Sink Not Required	-	Y
RM 27 Drinking Fountain (1-27-DF-1)	Room 27 - Weaving, Drinking Fountain	<b>28.3*</b>	-	<b>238</b>	Removed - Drinking Fountains Located Nearby in Hallway	-	Y
RM 29 Closet Sink (1-29-SINK-1)	Room 29 - Dance Room Closet	<b>447*</b>	-	<b>33.2</b>	Plumbing Cut & Capped, Fixture Left in Place	-	Y
RM 22 East Dish Sink (1-KIT-SINK-4)	Room 22 - Meals On Wheels, Kitchen Sink	<b>30.4*</b>	13.3	15.8	Clean screen quarterly	1.57	Y
RM 34 Sink (1-34-SINK-1)	Room 34 - Music Room, Sink	<b>61.6*</b>	9.34	-	Clean screen quarterly	-	Y
Cottage 3 Men's Bathroom - Center Sink (1-COT3-MLAV-2)	Cottage 3 - Men's Restroom, Center Sink	<b>20*</b>	6.36	-	Clean screen quarterly	-	Y
RM 11 Front Sink (1-11B-SINK-1)	Room 11 - Dark Room, Front Sink	<b>54.5*</b>	-	4.9	Sign "Do Not Drink, Not of Consumption"	-	Y



## Multnomah Arts Center water test results – December 2016

### Appendix A: Lead in Drinking Water Sampling Table

Location Description (Water Outlet Code)	Outlet Common Name	First Draw Results (ppb)	Post Screen- Cleaning First Draw Results (ppb)	Flush Results (ppb)	Remediation Action	Post Remediation First Draw Results (ppb)	Remediation Complete (Y/N)
RM 11 Back Sink (1-11A-SINK-1)	Room 11 - Dark Room, Back Sink	<b>22.3*</b>	-	3.1	Sign "Do Not Drink, Not of Consumption"	-	Y
RM 41 Kitchen Sink (1-41-KT-SINK-1)	Room 41 - Police Department Office, Kitchen Sink	10.5*	-	<b>33.8**</b>	Sign "Perform 2 Flush Prior to Drinking" ****	-	Y
EPA Recommended Lead Level for Drinking Water: 20 ppb							

\* Sampling conducted by the Portland Water Bureau

\*\* Collected by G2 to determine lead concentration at service connection

\*\*\* Results after 2 minute flush

\*\*\*\* G2 Consultants, Inc. verified the effectiveness of a two minute flush through additional water sampling.